

Drive shaft as removed with low spd shudder



alignment marks with shudder



Slip joint seal pulled back from spline joint



Fwd section DS rotated 90 deg away (note absence match mark out of view toward top)

