

MECHANISM AP17074 OR AP19630 AP19631	DUAL CYLINDER ROOM EXTENSION – 17.5" STROKE (WITH SYNC. CYLINDER) AP17073 KIT SEE > MR41.2005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP90456 (24.5" STROKE) REPLACES AP15344 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90439 (7.21" STROKE) REPLACES AP16618 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252
MECHANISM AP17077	SINGLE CYLINDER ROOM EXTENSION – 24.0" STROKE – AP17076 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP90688 (27.0" STROKE) REPLACES AP28362 HOSE ASSEMBLIES_____ ITEM 3 – RAP24632 (AP24632) ITEM 4 – RAP53984 (AP53984)
MECHANISM AP18113 AP18114	DUAL CYLINDER ROOM EXTENSION – 20.5" STROKE (WITH SYNCHRONIZING CYLINDER) AP18126 KIT SEE > MR41.2000.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP90617 (26.375" STROKE) REPLACES AP18124 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90616 (8.24" STROKE) REPLACES AP18122 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252
MECHANISM AP18738	SINGLE CYLINDER ROOM EXTENSION – 20.0" STROKE – AP18737 KIT NO INFORMATION AVAILABLE.
MECHANISM AP25142 AP25143	DUAL CYLINDER ROOM EXTENSION – 30.5" STROKE (WITH SYNCHRONIZING CYLINDER) AP25141 KIT SEE > MR41.2005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP90971 (37.5" STROKE) REPLACES AP25201 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90442 (12.570" STROKE) REPLACES AP16484 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252
MECHANISM AP26892 AP26893	LATERAL ARM ROOM EXTENSION – 18.0" STROKE (WITH TORSION BAR) – AP26891 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)
MECHANISM AP27707 AP27708	X –SLIDE ROOM EXTENSION – 17.75" STROKE – AP27706 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91007 (8.10" STROKE) REPLACES AP27723 TUBE KIT_____ ITEM 2 – RAP91229 – REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 – RAP24655 (AP24655) ITEM 5 – RAP24653 (AP24653)
MECHANISM AP28586 AP28587	LATERAL ARM ROOM EXTENSION – 16.0" STROKE – AP28585 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24641 (AP24641) ITEM 5 – RAP24642 (AP24642)

MECHANISM AP28776 AP28777	LATERAL ARM ROOM EXTENSION – 17.25" STROKE – AP28775 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24641 (AP24641) ITEM 5 – RAP24642 (AP24642)
MECHANISM AP28781 AP28782	LATERAL ARM ROOM EXTENSION – 17.625" STROKE – AP28780 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24651 (AP24651) ITEM 5 – RAP24652 (AP24652)
MECHANISM AP29855	GENERATOR SLIDE – 24.0" STROKE (CYLINDER ONLY) – AP29856 KIT CYLINDER ASSEMBLY_____ RAP92507 (24.0" STROKE) – REPLACES AP29855
MECHANISM AP30761	CYLINDER ASSEMBLY – 16.0" STROKE CYLINDER ASSEMBLY_____ RAP92470 (16.0" STROKE) – REPLACES AP30761
MECHANISM AP30763	CYLINDER ASSEMBLY – 30.0" STROKE CYLINDER ASSEMBLY_____ RAP91666 (30.0" STROKE) – REPLACES AP30763
MECHANISM AP30948 AP30949 OR AP31226	LATERAL ARM ROOM EXTENSION – 17.625" STROKE – AP30947 AND AP31225 KITS SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24655 (AP24655) ITEM 5 – RAP24653 (AP24653)
MECHANISM AP31690 AP31691	LATERAL ARM ROOM EXTENSION – 16.0" STROKE – AP31689 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91203 (6.150" STROKE) REPLACES AP26255 TUBE KIT_____ ITEM 2 – RAP91226 – REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 – RAP24648 (AP24648) ITEM 5 – RAP24650 (AP24650)
MECHANISM AP32165	SINGLE CYLINDER ROOM EXTENSION – 24.0" STROKE – AP32164 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91021 (27.0" STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 – RAP24632 (AP24632) ITEM 4 – RAP53984 (AP53984)
MECHANISM AP32003 AP32004	UNIVERSAL SLIDE OUT – 17.625" STROKE (WITH SYNCHRONIZING CYLINDER) AP32002 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91702 (34.0" STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90439 (7.21" STROKE) REPLACES AP16618 TUBE KIT_____ ITEM 2 – RAP91703 – REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 – RAP24638 (AP24638) ITEM 5 – RAP24632 (AP24632)
MECHANISM AP32006	SINGLE CYLINDER ROOM EXTENSION – 23.125" STROKE – AP32005 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 – RAP91021 (27.0" STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 4 – RAP24630 (AP24630) ITEM 3 – RAP24634 (AP24634)

MECHANISM AP32008 AP32009	UNIVERSAL FLAT OUT – AP32007 KIT NO INFORMATION AVAILABLE.
MECHANISM AP35083 AP35084	X-SLIDE ROOM EXTENSION – 17.75" STROKE – AP35082 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91007 (8.100" STROKE) REPLACES AP27723 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 - RAP24653 (AP24653) ITEM 5 - RAP24655 (AP24655)
MECHANISM AP35907 AP35908	X-SLIDE ROOM EXTENSION – 30.75" STROKE – AP35906 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91352 (13.90" STROKE) REPLACES AP27513 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 - RAP24653 (AP24653) ITEM 5 - RAP24655 (AP24655)
MECHANISM AP39096 AP39097	DUAL CYLINDER ROOM EXTENSION – 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) AP39095 KIT SEE > MR41.2005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92509 (31.0" STROKE) REPLACES AP39933 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.42" STROKE) REPLACES AP39271 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP39507 AP39508	UNIVERSAL LEVEL OUT – 30.0" STROKE – AP39435 KIT SEE > MR41.2690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 14 - CONTACT HWH CORPORATION TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) CENTER LIFT CYLINDER_____ ITEM 16 - CONTACT HWH CORPORATION
MECHANISM AP40226 AP40227	UNIVERSAL STRAIGHT OUT – 18.0" STROKE – AP40172 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92075 (20.5" STROKE) REPLACES AP39251 TUBE KIT_____ ITEM 2 - RAP92092 - REPLACES AP39321 HOSE ASSEMBLIES_____ ITEM 4 - RAP24662 (AP24662) ITEM 5 - RAP24664 (AP24664)
MECHANISM AP41642 AP41643	UNIVERSAL STRAIGHT OUT – 18.0" STROKE – AP41534 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24658 (AP24658) ITEM 5 - RAP24660 (AP24660)