

2005 Alpine Coach with HWH Jacks

Problem: DS rear jack would not retract without pry

Solution: Put additional springs inside HWH spring

create more lifting power. Worked great

Gadgets I used to stretch springs so they could be

Century Spring Corp. (800-237-5225) Part Number 5582 \$

Come Along

Floor Jack

1/8" Cable

HWH Jack Foot

Homemade Gadget

