2768 **Odometer:25273**

10/27/21 2:23 PM

wade griffin

josh and stephen

Heavy Duty Vehicles : Motorhome Chassis : Tiffin Motorhomes : Allegro Bus : 2010-
Total Alignment Without Caster on Rear Axles, 6 sensors

Front Axle 1 : Left

Actual	Before	Specified Range
0.9°*	0.9°*	-0.5° 0.5°
5.4°*	5.4°*	2.0° 3.0°
0.07°*	-0.01°*	0.00° 0.06°

Camber	
Caster	
Toe	
SAI	
Included Angle	
Turning Angle Diff.	

Front Axle 1 : Right

Actual	Before	Specified Range
0.3°	0.3°	-0.5° 0.5°
5.4°*	5.4°*	2.0° 3.0°
-0.01°*	-0.03°*	0.00° 0.06°

Front Axle 1

	Actual	Before	Specified Range
Cross Camber	0.6°	0.6°	
Cross Caster	0.0°	0.0°	
Cross SAI			
Total Toe	0.06°	-0.04°*	0.00° 0.13°
Cross Turn Diff.			

Rear Axle 1 : Left

Actual	Before	Specified Range
0.0°	0.0°	
0.26°	0.28°	

Camber
Toe

Rear Axle 1 : Right

Actual	Before	Specified Range
-0.3°	-0.3°	
-0.28°	-0.27°	

Rear Axle 1

	Actual	Before	Specified Range
Cross Camber	0.3°	0.3°	
Total Toe	-0.02°	0.02°	
Thrust Angle	0.27°*	0.28°*	-0.08° 0.08°

* This value is not within specification. Tire wear, handling and safety problems may result.