


# Roof Exterior

The visible condition of exterior coverings, trim, seals and drainage are inspected with respect to their effect on the condition of the RV.

Roof Type:

Fiberglass

Condition: Acceptable (A)



Front Cap, Joints And Seals:

Seals in good condition, Molding over cap

Condition: Acceptable (A)

